

CASE HISTORY

Franciscan Kitchen

The Challenge: The existing tile floor was failing badly creating a very difficult surface to clean, maintain and keep sanitary. Along with the tile floor failing, the wall systems that were in place were old, porous, damaged and nearly impossible to clean. This client required a seamless floor and wall system that would be durable, sanitary, easily maintained and hold up to the rigorous demands of a working kitchen.



The Solution: ESPOSITO LLC was chosen as a TRUN-KEY contractor to remove the existing floors and repair the damaged walls. ESPOSITO LLC was chosen to install a new Urethane based floor system with 6" sanitary cove base to withstand the abuse and heat generated in a full operations kitchen. ESPOSITO LLC was also chosen to install a seamless, fiberglass reinforced epoxy wall system that is easily maintained and durable.



ESPOSITO LLC removed the tile and existing mud base to expose the concrete substrate. ESPOSITO LLC the installed a ¼” urethane top coat the withstands up to 200 degree exposures on a consistent basis.



ESPOSITO LLC then applied a 3 coat system with fiberglass reinforcement to all applicable wall surfaces. The customer received a high performance floor and wall system that will last under the harsh abuses for many years.